

## 1 Products affected

Product hierarchy no. *			Part no.	SBU	Type / Description	Customer part no.
SBU	PG	PGU	Type			
02	007	060	0000002300	0909.0001	Connectors	0909, 2 x IEC Appliance Outlets F
02	007	060	0000002300	0909.0011	Connectors	0909, 3 x IEC Appliance Outlets F
02	007	060	0000002300	0909.0021	Connectors	0909, 4 x IEC Appliance Outlets F
02	007	060	0000002300	0909.0031	Connectors	0909, 5 x IEC Appliance Outlets F
02	007	060	0000002300	0909.0041	Connectors	0909, 6 x IEC Appliance Outlets F
02	007	060	0000002300	0909.0051	Connectors	0909, 7 x IEC Appliance Outlets F


\*SBU (2-digit) / PG (3-digit) / PGU (3-digit) / Type (10-digit)

## 2 Type of change

- L and N bars newly riveted to contacts, now are all 3 bars (L/N/E) riveted.
- Position of solder terminals of L&N are moved approx 5mm towards the border of the connector.

## 3 Detailed description of change


The old version had only the earth bar riveted to the outlet contacts - L/N bars and contacts were made of one piece. The new version has L/N/E riveted. (The holes are the riveting joints)



### 0909 Multiple IEC Appliance Outlets F

Release date:	Released by:					
24.5.2011	SHO					1 von 2

Position of solder terminals of L&N are moved approx 5mm towards the border of the connector.



**4 Reason of change**

Production improvement.

**5 Released date**

Release date: February 2011

**6 Impact of change and recommended action**

Form: New internal joining technique, solder terminals of L&N are moved approx 5mm towards the border of the connector.  
 Fit: No influence  
 Function: No influence  
 Production Site: No influence

**7 Reference Documents / Attachments**

Kind of document	Document number	Remarks