

## 1 Products affected

Product hierarchy no. *				Part no.	SBU	Type / Description	Customer part no.
SBU	PG	PUG	Type				
01	002	010	0000000504	See list below	Circuit protection	FPG5	n.a.



\*SBU (2-digit) / PG (3-digit) / PUG (3-digit) / Type (10-digit)

List of part numbers affected							
<b>FPG5 complete</b>							
3101.0050	3101.0055						
<b>FPG5 socket</b>							
3101.5015.1							
<b>FPG5 carrier</b>							
3101.8011	3101.8012	3101.8511					

## 2 Type of change

- Change of markings

## 3 Detailed description of change

Old product appearance	New product appearance
	

## 4 Reason of change

- Enhanced rated voltage approved according to UL 4248-1 and CSA C22.2 no. 4248.1

## 5 Release date

The change will be rolled-out starting ww 09/2017 (Date code 1709 or higher on label) and lasts approx. 6 months depending on the variant.

## 6 Impact of change and recommended action

Form	Yes	Modified marking on product
Fit	No	No change for dimension
Function	No	No change in function
Manufacturing	No	No change for manufacturing site
Label	No	No change on label
Packaging	No	No change in packaging

## 7 Reference Documents / Attachments

Kind of document	Remarks
<a href="#">Data Sheet</a>	

Product Change Notification					FPG5 marking change		
owner	creation date	release date	released by	change order no	rev	page	D10-010-919
dislercy	2017-08-02	2017-08-02	nowakfr	2013402	B	1 of 1	