





**1 Products affected**

Product hierarchy no. *			Part no.	SBU	Type / Description	Customer part no.	
SBU	PG	PGU	Type				
80	080	001	0000006179	FMBC-A91U-071x	EMC	FMBC NEO FILTER 3PH	
80	080	001	0000006179	FMBC-A91C-161x	EMC	FMBC NEO FILTER 3PH	
80	080	001	0000006179	FMBC-A91Q-301x	EMC	FMBC NEO FILTER 3PH	
80	080	001	0000006179	FMBC-A91R-421x	EMC	FMBC NEO FILTER 3PH	
80	080	001	0000006179	FMBC-A91S-551x	EMC	FMBC NEO FILTER 3PH	
80	080	001	0000006179	FMBC-A91F-751x	EMC	FMBC NEO FILTER 3PH	
80	080	001	0000006179	FMBC-A91G-J01x	EMC	FMBC NEO FILTER 3PH	
80	080	001	0000006179	FMBC-A91G-J31x	EMC	FMBC NEO FILTER 3PH	
80	080	001	0000006179	FMBC-A91V-J81x	EMC	FMBC NEO FILTER 3PH	
80	080	001	0000006195	FMAC-091C-1610	EMC	FMAC ECO FILTER 3PH	
80	080	001	0000006195	FMAC-091C-2510	EMC	FMAC ECO FILTER 3PH	
80	080	001	0000006195	FMAC-091E-6410	EMC	FMAC ECO FILTER 3PH	
80	080	001	0000006195	FMAC-091G-H110	EMC	FMAC ECO FILTER 3PH	
80	080	001	0000006195	FMAC-091G-H210	EMC	FMAC ECO FILTER 3PH	

\*SBU (2-digit) / PG (3-digit) / PGU (3-digit) / Type (10-digit)  
x = 0 or 2

**2 Type of change**

Old position of ventilation slots	New position of ventilation slots
	
	

**3 Detailed description of change**

Ventilation slots shifted from filters lateral side to top side of housing.

FMBC NEO, FMAC ECO					0118.2077	
Creation date:	Created by:	Release date:	Released by:	Notification No.	Index	Page
16.09.2011 08:31:54	BLU	16.09.2011	BLU	22331	-	1 von 2

#### 4 Reason of change

Improved heat dispersion.

#### 5 Released date

Januar 2011

#### 6 Impact of change and recommended action

Form: No influence  
Fit: No influence  
Function: No influence  
Production Site: No influence

#### 7 Reference Documents / Attachments

Kind of document	Document number	Remarks

FMBC NEO, FMAC ECO					0118.2077	
Creation date:	Created by:	Release date:	Released by:	Notification No.	Index	Page
16.09.2011 08:31:54	BLU	16.09.2011	BLU	22331	-	2 von 2